

Work Order ID 93950

December-07-12 2:23:15 PM

93950

Page 1

Item ID: D350-607-511

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Quick Release Basket Mounting Installation

Start Date: 11/27/12 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 11/28/12 Req'd Qty: 1.00 ***1***

Customer: CU-DAR001

Reference: RMA RA111449 - RETURN

Approvals: Process Plan: *[Signature]* Date: _____

Tooling: _____

Date: _____

Run

Start

NR1

QC: _____ Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D350-607-3	A

100

0.00

100

QC

Quality Control

Memo

INSPECT RA111449

1 X D350-607-511 B87122 CHG002

0.00

110

Identify as per dwg & Stock Location: PKG 012 0.00

110

Packaging

Packaging

Memo

REPACKAGE PER PPP USING NEW B/N
NEW LABELS AND PAPERWORK REQ'D

0.00

120

QC21- Final Inspection - Work Order Release 0.00

120

QC

Quality Control

Memo

0.00


(DAS 16) 12/11/12

(21)

12/12/11 *(DAS 20 9-8)*

@ CHG002 forms 12-12-10

12/12/11 *me* *12-12-11*



RA111449 D350-607-511

B87122

Received @ Dart November 23rd, 2012
Inspected @ Dart November 26th, 2012

Customer: HELISTREM INC
Customer Contact: MARK PISKURA
Shipped from: COSTA MESA CA, USA

Instructions for RA 111449 D350-607-511 B87122 CHG002

- Kit is complete
- Needs new paper work and labels
- Needs new BATCH # to go back into stock
- Needs new work order

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

QTY INSPECTED = x1

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**

